

ABN 54 058 675 620

5 Buna Place ALLAMBIE HTS 2100

Phone: +61 2 9975 6475 email: service@locktec.com.au

Fujitsu ScanSnap iX and S Series RTB Scanners Three Year Warranty Upgrades February 2021

On-site warranty offerings are not available for the ScanSnap iX and S Series RTB (Return To Base) scanners from Fujitsu or Locktec, please refer to Appendix "A" below. Neither Locktec nor Fujitsu sanctions any non-authorised third-party offerings of extended RTB or on-site warranties*.

Fujitsu ScanSnap iX and S Series RTB Standard Three-year RTB Warranty Offering

Applicable models: iX100, S1100i, S1300i, iX1400, iX1500, iX1600, SV600

Standard Terms and Conditions

The limited warranty set forth on this extended warranty is provided by Locktec Australia Pty Ltd (here on known as Locktec) with respect to the Fujitsu scanner and the original purchaser (customer). With the optional 2 (Two) Year Warranty Upgrade on top of the factory one-year return to base warranty. Locktec warrants that the scanner shall be free from defects in materials and workmanship excluding consumables for a total of (3) Three Years on parts and labour. At its option, Locktec will repair or replace at no charge, excluding consumables, Fujitsu scanner products which prove to be defective within the warranty period. This limited warranty shall not apply if the scanner has been damaged by unreasonable use, accident, negligence, improper packaging during shipment or modification by anyone other than a Fujitsu authorised service technician or by any other causes unrelated to defective materials or workmanship. To receive inwarranty service, a defective product must be delivered, prepaid, to the Locktec service centre only no later than (2) Two Weeks after the end of the warranty period. Locktec is responsible for freight and insurance for products returned to the customer.

We highly recommend that you insure the shipment as Locktec is not liable for damage in transit.

Locktec has the right to ask for proof of purchase; failure to supply proof of purchase when requested may jeopardise the warranty. In addition, a Return Authorisation (RA) number must be obtained and be clearly container. To displayed on the shipping obtain your RAnumber https://www.locktec.com.au/service-requests/. All delivery costs or shipping charges to return defective product under the warranty policy must be prepaid. Locktec is not responsible for any damage to products if they are shipped to us in non-original packaging. Locktec is not responsible and assumes no liability for any loss or damage occurred during shipment. Insuring product for its value is the responsibility of the purchaser. Repackage the scanner in its original packaging or in a sturdy cardboard box with sufficient packing foam. Items physically damaged in transit are NOT covered by warranty. Defective parts or a defective scanner will be repaired or exchanged for comparable parts of equal value.

EXCEPT FOR THE EXPRESSED WARRANTY STATED ABOVE, LOCKTEC AUSTRALIA PTY LTD MAKES NO OTHER WARRANTIES, WHETHER EXPRESSED OR IMPLIED.

Appendix A

Onsite warranty is not a practical option for the ScanSnap iX and S Series RTB Scanners.

- It is fiscally impractical to offer onsite service for ScanSnap iX and S Series scanners.
- It is not practical to provide documentation and training to personnel at national Fujitsu Service centre sites.
- The scanners are built extremely compact and require an intimate knowledge of the units to perform maintenance.
- The scanners are compact in size and light weight which makes them ideal for overnight transportation.

*Locktec Australia Pty Ltd is Fujitsu's authorised service provider for the ScanSnap iX and S series RTB scanners within Australia and New Zealand, third party repairers do not have access to factory support services, local support services, documentation or warranty replacement programs.

Customers who purchase third party warranties will be turned away and not provided with support outside the standard factory warranty.

General

- The terms and conditions are valid till the next issue and may be changed without notice, please contact Locktec Australia Pty Ltd on 1300 55 22 50 for updated information.
- All Locktec supported scanners carry a twelve months return to base warranty unless otherwise specified.
- Please don't hesitate to contact Locktec on 1300 55 22 50 or email service@locktec.com.au if further information is required.